

BOX ELDER

BOX ELDER, SD | PWSID: SD4600046 | Population served: 14,000
Based on EPA UCMR 5 testing data (2023-2025) | Report generated July 10, 2026



No PFAS compounds detected above reporting limits

The EPA set enforceable limits for six PFAS compounds in April 2024. Grade reflects the worst single compound result.

Findings

Compound	Detected (ppt)	EPA Limit (ppt)	Ratio	Status
No PFAS compounds were detected in EPA testing of this water system.				

What This Means

No PFAS compounds were detected in this system's testing. This does not guarantee the absence of PFAS, as testing covers specific compounds at specific detection limits.

What You Can Do

- Request your utility's full Consumer Confidence Report (CCR) for additional water quality data
- Consider an NSF 53 (pitcher) or NSF 58 (reverse osmosis) certified filter if PFAS were detected
- Attend your local water board or city council meeting to ask about treatment plans