

## SOUTH WEBER WATER SYSTEM

KAYSVILLE, UT | PWSID: UTAH06010 | Population served: 8,125

Based on EPA UCMR 5 testing data (2023-2025) | Report generated April 8, 2026



### No PFAS compounds detected above reporting limits

The EPA set enforceable limits for six PFAS compounds in April 2024. Grade reflects the worst single compound result.

### Findings

Compound	Detected (ppt)	EPA Limit (ppt)	Ratio	Status
No PFAS compounds were detected in EPA testing of this water system.				

### What This Means

No PFAS compounds were detected in this system's testing. This does not guarantee the absence of PFAS, as testing covers specific compounds at specific detection limits.

### What You Can Do

- Request your utility's full Consumer Confidence Report (CCR) for additional water quality data
- Consider an NSF 53 (pitcher) or NSF 58 (reverse osmosis) certified filter if PFAS were detected
- Attend your local water board or city council meeting to ask about treatment plans