# Water Quality Report Card

CheckYourWater.org

## OMND WATER TREATMENT PLANT

DICKINSON, ND | PWSID: ND2901491 | Population served: 4,168

Based on EPA UCMR 5 testing data (2023-2025) | Report generated November 25, 2026

A

### No PFAS compounds detected above reporting limits

The EPA set enforceable limits for six PFAS compounds in April 2024. Grade reflects the worst single compound result.

## Findings

| Compound | Detected (ppt) | EPA Limit (ppt) | Ratio | Status |
|---|---|---|---|---|
| No PFAS compounds were detected in EPA testing of this water system. | | | | |

## What This Means

No PFAS compounds were detected in this system's testing. This does not guarantee the absence of PFAS, as testing covers specific compounds at specific detection limits.

## What You Can Do

- Request your utility's full Consumer Confidence Report (CCR) for additional water quality data
- Consider an NSF 53 (pitcher) or NSF 58 (reverse osmosis) certified filter if PFAS were detected
- Attend your local water board or city council meeting to ask about treatment plans



This report is provided for informational purposes. It is not a substitute for professional water quality analysis.